

Report
On
The Trial Installation
Of
Central Products, STAC System
To
Pipe and Flange of Valve
At

Block 19A - Berth 13

**Port of Tanjung Pelepas** 

## Prepared and submitted by:



No. 6, Jalan TP 3/1, Taman Perindustrian Sime UEP, 47600 Subang Jaya, Selangor, Malaysia. Tel: +603-8011 9792 Fax: +603-8011 9793

Email: cpc.intl.my@gmail.com Website: www.beaver-entech.com



Report

0n

The Trial Installation

Of

**Central Products, STAC System** 

To

Pipe and Flange of Valve

At

Block 19A - Berth 13

**Port of Tanjung Pelepas** 

March 2015

Prepared and submitted by:



No. 6, Jalan TP 3/1, Taman Perindustrian Sime UEP, 47600 Subang Jaya, Selangor, Malaysia. Tel: +603-8023 9755 Fax: +603-8023 9455

Email: cpc.intl.my@gmail.com

# Report On The Trial Installation Of Central Products, STAC System To Pipe and Flange of Valve AtBlock 19A – Berth 13,Port of Tanjung Pelepas

#### **BACKGROUND:**

**Client** : Port of Tanjung Pelepas

**Vendor** : CP Coatings Sdn Bhd, Distributor of Central Products

**Description** : Diameter of pipe : 200mm and Flanged Valve

Length: total of 1200mm

Located in 2000mm deep manhole at Block 19A – Berth 13  $\,$ 

**Installation** : 27<sup>th</sup> March 2015

10.00am to 12.30pm (2.5 hours)

Based on the tide information, the low tide is at 9.00am

**Attended by** : Norman Ismail & Team PTP

Ling Liong Lai CP Coatings Sdn Bhd Sherman Chaw CP Coatings Sdn Bhd Bo Soon Leong STAC System Sdn Bhd

**Material Used** : STACprime,

STACfill,

STACwrap (100mm) and STACguard (100mm)

Manufactured By : Central Products LLC, USA (Central Products (Tianjin) Co Ltd)

#### **Site Pictures:**







## **Description and Condition of Site and Installation**

The installation concerns a Valve flanged connected to 200mm ductile iron pipe distributing potable water to the berths.

The valve and pipe are housed in a manhole of approximately  $1500 \text{mm} \times 1500 \text{mm} \times 2000 \text{mm}$  depth.

The manhole is often water logged especially during high tide.

The valve and flange is observed to be in good conditions with no signs of corrosion.

The flange mounted DI pipe shows sign of rust at the welded areas. The coating is flaking up and surface is dried up without protection.





#### **Trial Installation**

A trial installation of the corrosion protection materials by Central Products LLC, USA was proposed to demonstrate the effectiveness of the materials.

The installation at Block 19A, Berth 13 was identified by the client for this purpose.


The installation was about 2-3 years of age.

For comparison purpose, it was decided to carry out the wrapping of the pipe and flange of one side with the other not protected.

#### **Trial Installation Procedure**

The procedure of the installation is as follows:

- a. Inspection and preparation of site including removing the manhole covers.
- b. Remove dirt, grease, oil, excessive moisture and frost, loose rust, paint and foreign matter by hand tools from the pipe and the flange.
- c. Apply a thin, uniform film of STACprime UW over the entire surface to be wrapped with gloved hand, brush or rag.
  - Apply a liberal coating to displace surface moisture, passivate surface oxides, fill surface imperfections and ensure adhesion between STACwrap and the substrate.
- d. Apply STACfill by filling and packing to achieve a uniform contour to which tape can be applied without bridging or voids.
  - Use a putty knife or gloved hand to apply STACfill in voids, cavities, etc. Contour extremely uneven surfaces and remove air pockets.
- e. Apply two layer of STACwrap over the primed and filled surfaces.
- f. Apply two layer of STACguard overlap for Mechanical protection



## **Installation Pictures:**

Photo 01: View of site area




Photo 02 : Preparation




Photo 03: View of the pipe and flange



Photo 04 : Cleaning with hand tools



Photo 05: View of pipe and flange after clean



Photo 07: View after apply STACprime



Photo 09: View after apply STACfill



Photo 11: View of apply STACwrap



Photo 06: Apply STACprime



Photo 08: Apply STACfill on flange area



Photo 10: View after apply STACfill




Photo 12: View of apply STACwrap



Photo 13: View after apply STACwrap



Photo 14: View after apply STACguard



## **Notes:**

The STAC system was used on one side of the flange only to compare the difference between protected and none protected area.

STACguard was also installed on part of the wrapped area for comparison purposes.

It is recommended that the installation be inspected after 3 months to monitor the effectiveness of the materials.

## Attachment.

The technical information on the following is attached

- 1. STACprime
- 2. STACfill
- 3. STACwrap
- 4. STACguard

Prepared and Submitted by

**CP Coatings Sdn Bhd** 

March 2015